



solutions and action

**Interstate Power and Light Company**

Burlington Generating Station  
CCR Surface Impoundment Annual Inspection Report  
154.018.024.001  
Report issued: June 24, 2021

**Hard Hat Services**

ph: 877-630-7428  
hardhatinc.com  
932 N. Wright St., Suite 160  
Naperville, IL 60563

## Executive Summary

This annual inspection report has been prepared in accordance with the requirements of the United States Environmental Protection Agency published Final Rule for Hazardous and Solid Waste Management System - Disposal of Coal Combustion Residual (CCR) from Electric Utilities (40 CFR Parts 257 and 261, also known as CCR Rule).

This annual inspection report assesses the condition of existing CCR surface impoundments. Primarily, the annual inspection report is focused on the structural stability of the CCR surface impoundments and to ensure that the operation and maintenance of the CCR surface impoundments is in accordance with recognized and generally accepted good engineering standards.

After conducting the annual inspection, as well as review of available information pertaining to the status and condition of the existing CCR surface impoundments, and discussions with facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundments, there are no operating deficiencies and there have been no changes that have affected the stability or operation of the CCR surface impoundments since the previous annual inspection.

## Table of Contents

1.	INTRODUCTION.....	1
1.1	CCR Rule Applicability.....	1
1.2	Annual Inspection Applicability.....	1
2.	ANNUAL INSPECTION REPORTING CRITERIA.....	3
2.1	BGS Ash Seal Pond .....	3
2.1.1	Changes in Geometry (§257.83(b)(2)(i)).....	3
2.1.2	Existing Instrumentation (§257.83(b)(2)(ii)).....	3
2.1.3	Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii)) .....	4
2.1.4	Storage Capacity of Impounding Structure (§257.83(b)(2)(iv)).....	5
2.1.5	Volume of Impounded CCR and Water (§257.83(b)(2)(v)).....	6
2.1.6	Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi)) .....	7
2.1.7	Other Changes Affecting Stability or Operation of Impounding Structure (§257.83(b)(2)(vii)) .....	8
2.2	BGS Main Ash Pond .....	8
2.2.1	Changes in Geometry (§257.83(b)(2)(i)).....	8
2.2.2	Existing Instrumentation (§257.83(b)(2)(ii)).....	8
2.2.3	Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii)) .....	9
2.2.4	Storage Capacity of Impounding Structure (§257.83(b)(2)(iv)).....	11
2.2.5	Volume of Impounded CCR and Water (§257.83(b)(2)(v)).....	12
2.2.6	Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi)) .....	13
2.2.7	Other Changes Affecting Stability or Operation of Impounding Structure (§257.83(b)(2)(vii)) .....	14
2.3	BGS Economizer Pond.....	15
2.3.1	Changes in Geometry (§257.83(b)(2)(i)).....	15
2.3.2	Existing Instrumentation (§257.83(b)(2)(ii)).....	15
2.3.3	Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii)) .....	16
2.3.4	Storage Capacity of Impounding Structure (§257.83(b)(2)(iv)).....	18
2.3.5	Volume of Impounded CCR and Water (§257.83(b)(2)(v)).....	18

2.3.6 Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi)) ..... 19

2.3.7 Other Changes Affecting Stability or Operation of Impounding Structure  
(§257.83(b)(2)(vii)) ..... 20

2.4 BGS Upper Ash Pond..... 20

2.4.1 Changes in Geometry (§257.83(b)(2)(i)) ..... 20

2.4.2 Existing Instrumentation (§257.83(b)(2)(ii)) ..... 20

2.4.3 Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii)) ..... 21

2.4.4 Storage Capacity of Impounding Structure (§257.83(b)(2)(iv)) ..... 23

2.4.5 Volume of Impounded CCR and Water (§257.83(b)(2)(v))..... 23

2.4.6 Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi)) ..... 24

2.4.7 Other Changes Affecting Stability or Operation of Impounding Structure  
(§257.83(b)(2)(vii)) ..... 25

3. CERTIFICATION..... 26

## 1. INTRODUCTION

This annual inspection report has been prepared in accordance with the requirements of §257.83(b) of the United States Environmental Protection Agency (USEPA) published Final Rule for Hazardous and Solid Waste Management System – Disposal of Coal Combustion Residual (CCR), herein referenced as the CCR Rule.

### 1.1 CCR Rule Applicability

The CCR Rule requires annual inspections by a qualified professional engineer (PE) for existing CCR surface impoundments with a height of 5 feet or more and a storage volume of 20 acre-feet or more or the CCR surface impoundment has a height of 20 feet or more (40 CFR §§ 257.73(b), 257.73(d) and 257.83(b)).

### 1.2 Annual Inspection Applicability

The Interstate Power and Light Company (IPL), Burlington Generating Station (BGS) in Burlington, Iowa has four existing CCR surface impoundments that meet the requirements of Section 1.1, identified as follows:

- BGS Ash Seal Pond
- BGS Main Ash Pond
- BGS Economizer Pond
- BGS Upper Ash Pond

The CCR surface impoundments have been assigned a state identification number by the Iowa Department of Natural Resources (IDNR), which is 29-UDP-01-15.

The annual inspection of the CCR surface impoundments at BGS was completed by a qualified PE on May 18, 2021. The annual inspection was

completed to ensure that the design, construction, operation, and maintenance of the CCR surface impoundments at BGS are consistent with recognized and generally accepted good engineering standards.

The annual inspection of the CCR surface impoundments at BGS included a review of available information regarding the status and condition of the CCR surface impoundments. The information reviewed included all relevant files available in the operating record at the time of the annual inspection, as well as the Alliant Energy CCR Rule Compliance Data and Information website entries for BGS ([ccr.alliantenergy.com](http://ccr.alliantenergy.com)). These files for the CCR surface impoundments at BGS include, but is not limited to, CCR surface impoundment design and construction information (history of construction), hazard potential classification, structural stability assessment, safety factor assessment, hydrologic and hydraulic capacities (inflow flood control plan), results of 7-day inspections and instrumentation monitoring by a qualified person, and results of the previous annual inspection.

The annual inspection also included a visual inspection of the CCR surface impoundments to identify signs of distress or malfunction of the CCR surface impoundments and appurtenant structures. Additionally, the visual inspection included hydraulic structures underlying the base of the CCR surface impoundments or passing through the dikes of the CCR surface impoundments for structural integrity and continued safe and reliable operation.

## 2. ANNUAL INSPECTION REPORTING CRITERIA

The following sub-sections address the annual inspection reporting criteria per §257.83(b)(2) of the CCR Rule for the existing CCR surface impoundments located at BGS.

### 2.1 BGS Ash Seal Pond

#### 2.1.1 Changes in Geometry (§257.83(b)(2)(i))

After conducting the annual inspection, as well as review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, and discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no identified changes in the geometry since the previous annual inspection.

#### 2.1.2 Existing Instrumentation (§257.83(b)(2)(ii))

Instrumentation that supports the operation of the BGS Ash Seal Pond includes a staff gauge to monitor the water elevation of the CCR surface impoundment. The impoundment is operated as an infiltration basin. The staff gauge, installed in October 2016, is in the southwest corner of the BGS Ash Seal Pond. The staff gauge was not installed at the lowest point within the impoundment; therefore, it is possible to observe no reading on the staff gauge when stormwater is accumulated in the lowest point of the impoundment.

The staff gauge water elevation data, since the previous annual inspection, was provided by IPL. The staff gauge measurements were collected at the same time as the 7-day inspections. The water elevation data included

measurements collected between April 2, 2020 and March 30, 2021. Review of the provided staff gauge water elevation data indicated that the water elevation was below the bottom of the staff gauge during the 7-day inspections for most of the period. The maximum water elevation recorded within the BGS Ash Seal Pond was 532.40 feet (March 30, 2021).

### **2.1.3 Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii))**

The approximate minimum, maximum, and present depths and elevations of the impounded CCR and water in the BGS Ash Seal Pond since the previous annual inspection were determined using information that was collected during the annual inspection, as well as from historical information that was previously provided from IPL.

The historical information provided from IPL included staff gauge water elevation data since the previous annual inspection, a drawing of the original structural site preparation grading plan contours of the BGS Ash Seal Pond prepared by Black & Veatch (1965), as well as the most recent topographic/bathymetric survey of the BGS Ash Seal Pond completed by French-Reneker-Associates (2016). Reviewing the information provided within the above-mentioned documents, the following minimum, maximum, and present depths and elevations were approximated for the impounded CCR and water:

- At the time of the annual inspection, water was not observed to be present within the BGS Ash Seal Pond. Therefore, the minimum and present depth and elevation of water within the CCR surface impoundment was unable to be determined.
- From staff gauge water elevation data provided by IPL since the previous annual inspection, the maximum water elevation was



532.40, which is 1.6 feet below the crest of the south embankment which has an elevation of approximately 534 feet.

- From the 2016 topographic/bathymetric survey of the BGS Ash Seal Pond, the elevation of the top of CCR/sediment varied between an elevation of 529 feet in the southwest corner of the CCR surface impoundment to an elevation of 536 feet in the northeast corner of the CCR surface impoundment. The average elevation of the top of CCR/sediment within the BGS Ash Seal Pond was approximately 532.5 feet.
- From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation of the BGS Ash Seal Pond was approximately 12 feet below the top of crest of the south embankment at an elevation of 521 feet. Comparing the 2016 topographic/bathymetric survey top of CCR/sediment elevations to the 1965 drawing of the original structural site preparation grading plan bottom contour elevation, the deposition thickness of the BGS Ash Seal Pond varied between 8 feet in the southwest corner to 15 feet in the northeast corner of the CCR surface impoundment.

#### **2.1.4 Storage Capacity of Impounding Structure (§257.83(b)(2)(iv))**

The storage capacity (i.e. water volume) of the CCR surface impoundment at the time of the annual inspection was estimated from the acreage of the CCR surface impoundment and the historical depth of water when it was present.

At the time of the annual inspection, water was not observed within the BGS Ash Seal Pond. However, historical information previously provided from IPL staff allowed for the calculation of the historical water volume of the BGS Ash Seal Pond. From a topographic survey completed by Smith Engineering (2008), the normal operating surface water elevation of the BGS Ash Seal

Pond was approximately 531.5 feet. From the 2016 topographic/bathymetric survey data, the area of the water surface at elevation 531.5 feet is approximately 2.45 acres. The estimated average top of CCR/sediment elevation within the BGS Ash Seal Pond, in the area where water is present at an elevation of 531.5 feet, was 530.25 feet. Comparing the 2008 topographic survey normal operating surface water elevation (531.5 feet) to the 2016 topographic/bathymetric survey of the top of the CCR/sediment (530.25 feet), the depth of water within the BGS Ash Seal Pond was approximately 1.25 feet. Thus, the water volume within the BGS Ash Seal Pond, based on historical information, is approximately 5,000 cubic yards.

### **2.1.5 Volume of Impounded CCR and Water (§257.83(b)(2)(v))**

The volume of impounded CCR and water (i.e. total volume, not including freeboard) within the BGS Ash Seal Pond at the time of the annual inspection was determined using information that was collected at the time of the annual inspection, as well as from historical information that was previously provided from IPL.

At the time of the annual inspection, water was not observed in the BGS Ash Seal Pond. Therefore, only the total volume of impounded CCR, and not total volume of CCR and water, could be determined.

The approximate volume of impounded CCR in the BGS Ash Seal Pond was calculated using historical information provided from IPL, which included a drawing of the original structural site preparation grading plan contours of the BGS Ash Seal Pond prepared by Black & Veatch (1965), as well as the most recent topographic/bathymetric survey of the BGS Ash Seal Pond completed by French-Reneker-Associates (2016).

From the 2016 topographic/bathymetric survey of the BGS Ash Seal Pond, the average elevation of the top of CCR/sediment was approximately 532.5 feet. From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation of the BGS Ash Seal Pond was approximately 12 feet below the top of crest of the south embankment at elevation 521 feet. Thus, the interior storage height of the BGS Ash Seal Pond was estimated to be approximately 11.5 feet.

The surface area of the BGS Ash Seal Pond was approximately 5.7 acres. Thus, the total volume of impounded CCR, not including freeboard, within the BGS Ash Seal Pond at the time of the annual inspection was approximately 106,000 cubic yards.

### **2.1.6 Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, as well as conducting the on-site visual inspection of the existing CCR surface impoundment, there have been no identified appearances of an actual or potential structural weakness of the existing CCR surface impoundment and appurtenant structures.

Regarding the existing conditions of the BGS Ash Seal Pond, there were no existing conditions identified along the upstream and downstream slopes of the embankments that were disrupting or have the potential to disrupt the operation and safety of the existing CCR surface impoundment.

### **2.1.7 Other Changes Affecting Stability or Operation of Impounding Structure (§257.83(b)(2)(vii))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, as well as discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no other identified changes that have affected the stability or operation of the BGS Ash Seal Pond since the previous annual inspection.

## **2.2 BGS Main Ash Pond**

### **2.2.1 Changes in Geometry (§257.83(b)(2)(i))**

After conducting the annual inspection, as well as review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, and discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no identified changes in the geometry since the previous annual inspection.

### **2.2.2 Existing Instrumentation (§257.83(b)(2)(ii))**

Instrumentation that supports the operation of the BGS Main Ash Pond includes a staff gauge to monitor the water elevation of the CCR surface impoundment. The staff gauge, installed in October 2016, is in the northwest corner of the BGS Main Ash Pond.

The staff gauge water elevation data, since the previous annual inspection, was provided by IPL. The staff gauge measurements were collected at the same time as the 7-day inspections. The water elevation data included measurements collected between April 2, 2020 and March 30, 2021. After

review of the provided staff gauge water elevation data, the maximum water elevation recorded within the BGS Main Ash Pond was 531.77 feet (January 5, 2021).

### **2.2.3 Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii))**

The approximate minimum, maximum, and present depths and elevations of the impounded CCR and water in the BGS Main Ash Pond since the previous annual inspection were determined using information that was collected during the annual inspection, as well as from historical information that was previously provided from IPL.

At the time of the annual inspection, a survey was completed to determine the present surface water elevation of the CCR surface impoundment. Additionally, depth measurements from the water surface to the top of CCR/sediment were obtained to determine present depths/elevations.

The historical information provided from IPL included staff gauge water elevation data since the previous annual inspection, a drawing of the original structural site preparation grading plan contours of the BGS Main Ash Pond prepared by Black & Veatch (1965), as well as the most recent topographic/bathymetric survey of the BGS Main Ash Pond completed by French-Reneker-Associates (2016). Reviewing the information provided within the above-mentioned documents, as well as the data collected during the annual inspection, the following minimum, maximum, and present depths and elevations were approximated for the impounded CCR and water:

- The area of normally impounded water within the BGS Main Ash Pond is in the northwest corner of the CCR surface impoundment. The surface area of the impounded water is approximately 0.46 acres of the approximate 18.9 acres that makes up the BGS Main Ash

Pond. At the time of the annual inspection, the water surface elevation was observed to have a staff gauge elevation of 531.57 feet, 1.43 feet below the crest of the west embankment which has an elevation of approximately 533 feet.

- At the time of the annual inspection, the water depths that were measured within the CCR surface impoundment varied between 2.8 feet and 4.2 feet.
- From the water depth measurements at the time of the annual inspection, the elevation of the top of the CCR/sediment that was measured varied between an elevation of 528.8 feet and 527.4 feet.
- From staff gauge water elevation data provided by IPL since the previous annual inspection, the minimum water elevation within the BGS Main Ash Pond was recorded to be 530.91 feet (March 23, 2021). The maximum water elevation within the BGS Main Ash Pond was recorded to be 531.77 feet (January 5, 2021).
- From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation that was present prior to the construction of the BGS Main Ash Pond was approximately 524 feet. Comparing the results from the water depth measurements at the time of the annual inspection to the 1965 drawing of the original structural site preparation grading plan bottom contour elevation, the deposition thickness in the area of normally impounded water within the northwest corner of the BGS Main Ash Pond varied between 4.8 feet and 3.4 feet.
- Of the 18.9 acres that makes up the surface area of the BGS Main Ash Pond, approximately 18.44 acres consists of CCR/sediment and does not normally consist of impounded water. From the 2016

topographic/bathymetric survey of the BGS Main Ash Pond, the elevation of the top of CCR/sediment varied throughout the CCR surface impoundment, as follows:

- In the western half of the BGS Main Ash Pond (i.e. non-CCR operational area), the top of CCR/sediment elevation varied between 532 feet and 536 feet. Comparing the 2016 topographic/bathymetric survey top of CCR/sediment elevations to the 1965 drawing of the original structural site preparation grading plan bottom contour elevation, the deposition thickness of the BGS Main Ash Pond in the western half of the CCR surface impoundment varied between 8 feet to 12 feet.
- In the eastern half of the BGS Main Ash Pond (i.e. CCR operational area), the top of CCR/sediment elevation varied between 534 feet and 563 feet. Comparing the 2016 topographic/bathymetric survey top of CCR/sediment elevations to the 1965 drawing of the original structural site preparation grading plan bottom contour elevation, the deposition thickness of the BGS Main Ash Pond in the eastern half of the CCR surface impoundment varied between 10 feet to 39 feet.

#### **2.2.4 Storage Capacity of Impounding Structure (§257.83(b)(2)(iv))**

The storage capacity (i.e. water volume) of the CCR surface impoundment at the time of the annual inspection was calculated based on the acreage of the CCR surface impoundment in the area where water is present, and the approximate depth of water within that area of the CCR surface impoundment. The water depth measurements of the CCR surface impoundment were collected at the time of the annual inspection.

At the time of the annual inspection, the open water present within the BGS Main Ash Pond was in the northwest corner of the CCR surface impoundment. From the 2016 topographic/bathymetric survey data, the area of the water surface located in the northwest corner of the CCR surface impoundment was approximately 0.46 acres. From the water depth data that was collected during the annual inspection, the average water depth within the northwest corner of the CCR surface impoundment was approximately 3.75 feet. Thus, the water volume within the northwest corner of the BGS Main Ash Pond at the time of the annual inspection was approximately 2,800 cubic yards.

### **2.2.5 Volume of Impounded CCR and Water (§257.83(b)(2)(v))**

The volume of impounded CCR and water (i.e. total volume, not including freeboard) within the BGS Main Ash Pond at the time of the annual inspection was determined using information that was collected during the annual inspection, as well as from historical information that was previously provided from IPL.

Historical information provided from IPL included a drawing of the original structural site preparation grading plan contours of the BGS Main Ash Pond prepared by Black & Veatch (1965), as well as the most recent topographic/bathymetric survey of the BGS Main Ash Pond completed by French-Reneker-Associates (2016). IPL reported that 7,063 tons of hydrated fly ash were removed from the eastern portion of the CCR surface impoundment for beneficial use since the most recent topographic/bathymetric survey was completed in 2016. Therefore, the calculated volume based on the 2016 survey is greater than the actual volume of impounded CCR and water that was present at the time of the annual inspection.



From the 2016 topographic/bathymetric survey of the BGS Main Ash Pond, the average elevation of the top of CCR/sediment in the western portion of the CCR surface impoundment (i.e. non-CCR operational area) was approximately 534.5 feet. The average elevation of the top of CCR/sediment in the eastern portion of the CCR surface impoundment (i.e. CCR operational area) was approximately 544 feet. From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation that was present prior to the construction of the BGS Main Ash Pond was approximately 524 feet. Thus, the interior storage height of the western portion of the CCR surface impoundment was approximately 10.5 feet and the interior storage height of the eastern portion of the CCR surface impoundment was approximately 20 feet.

The surface area of the western portion of the BGS Main Ash Pond was approximately 10.9 acres. Thus, the volume of impounded CCR and water within the western portion of the BGS Main Ash Pond was approximately 185,000 cubic yards. The surface area of the eastern portion of the BGS Main Ash Pond was approximately 8 acres. Thus, the volume of impounded CCR and water within the eastern portion of the BGS Main Ash Pond was approximately 258,000 cubic yards. The total volume of impounded CCR and water within the BGS Main Ash Pond at the time of the annual inspection was approximately 443,000 cubic yards.

### **2.2.6 Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, as well as conducting the on-site visual inspection of the existing CCR surface impoundment, there have been no identified appearances of an actual or

potential structural weakness of the existing CCR surface impoundment. Additionally, there were no identified issues with the structural integrity of the hydraulic structures (two corrugated metal pipe culverts) associated with the BGS Main Ash Pond.

Regarding the existing conditions of the BGS Main Ash Pond, there were no existing conditions identified along the upstream and downstream slopes of the embankments that were disrupting or have the potential to disrupt the operation and safety of the existing CCR surface impoundment.

### **2.2.7 Other Changes Affecting Stability or Operation of Impounding Structure (§257.83(b)(2)(vii))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, as well as discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no new identified changes that have affected the stability or operation of the BGS Main Ash Pond since the previous annual inspection.

During the annual inspection, a seep area in the southeast corner of the impoundment was observed. This area has been monitored by the facility staff since the discovery for worsening conditions or for any other issues that could affect the stability or operations of the impoundment. The seep area appears to have widened along the base of the exterior berm and is approximately one hundred feet long and extends up about one third of the embankment height. In two areas, sloughing was observed approximately six feet wide and two feet in depth. To maintain long term stability of the impoundment, this area should be adequately repaired according to good engineering and maintenance practices as site conditions allow. Until the

repair is completed, this area should continue to be closely monitored during the routine inspections by the facility staff and immediate actions should be taken if conditions worsen.

## 2.3 BGS Economizer Pond

### 2.3.1 Changes in Geometry (§257.83(b)(2)(i))

After conducting the annual inspection, as well as review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, and discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no identified changes in the geometry since the previous annual inspection.

### 2.3.2 Existing Instrumentation (§257.83(b)(2)(ii))

Instrumentation that supports the operation of the BGS Economizer Pond includes a staff gauge to monitor the water elevation of the CCR surface impoundment. The staff gauge, installed in October 2016, is in the southwest corner of the BGS Economizer Pond.

The staff gauge water elevation data, since the previous annual inspection, was provided by IPL. The staff gauge measurements were collected at the same time as the 7-day inspections. The water elevation data included measurements collected between April 2, 2020 and March 30, 2021. After review of the provided staff gauge water elevation data, the maximum water elevation recorded within the BGS Economizer Pond was 547.2 feet (August 27, 2020).

### 2.3.3 Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii))

The approximate minimum, maximum, and present depths and elevations of the impounded CCR and water in the BGS Economizer Pond since the previous annual inspection were determined using information that was collected during the annual inspection, as well as from historical information that was previously provided from IPL.

At the time of the annual inspection a survey was completed to determine the present surface water elevation of the CCR surface impoundment. Additionally, depth measurements from the water surface to the top of CCR/sediment were obtained to determine present depths/elevations.

The historical information provided from IPL included staff gauge water elevation data since the previous annual inspection, a drawing of the original structural site preparation grading plan contours prepared by Black & Veatch (1965) which show the original contours prior to the construction of the BGS Economizer Pond, as well as the most recent topographic/bathymetric survey of the BGS Economizer Pond completed by French-Reneker-Associates (2016). Reviewing the information provided within the above-mentioned documents, as well as the collected field data during the annual inspection and the 2017 annual inspection, the following minimum, maximum, and present depths and elevations were approximated for the impounded CCR and water:

- At the time of the annual inspection, the water surface elevation was surveyed to be 546.22 feet, 1.33 feet below the crest of the south side of the CCR surface impoundment which had an elevation of 547.55 feet at that location.

- At the time of the annual inspection, the water depths that were measured within the CCR surface impoundment varied between 1.8 feet and 3.5 feet.
- From the water depth measurements at the time of the annual inspection, the elevation of the top of CCR/sediment that was measured varied between an elevation of 544.4 feet and 542.7 feet.
- From staff gauge water elevation data provided by IPL since the previous annual inspection, the minimum water elevation within the BGS Economizer Pond was recorded to be 546.1 feet (March 16, 2021). The maximum water elevation within the BGS Economizer Pond was recorded to be 547.2 feet (August 27, 2020).
- From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation that was present prior to the construction of the BGS Economizer Pond was approximately 521 feet. Comparing the results from the water depth measurements at the time of the annual inspection to the 1965 drawing of the original structural site preparation grading plan bottom contour elevation, the deposition thickness within the BGS Economizer Pond varied between 23.4 feet and 21.7 feet.
- From the 2016 topographic/bathymetric survey, the top of CCR elevation along the economizer embankment varied between 546 feet and 550 feet. Comparing the 2016 topographic/bathymetric survey top of CCR elevations to the 1965 drawing of the original structural site preparation grading plan bottom contour elevation, the deposition thickness of the economizer embankment varied between 25 feet to 29 feet.

#### **2.3.4 Storage Capacity of Impounding Structure (§257.83(b)(2)(iv))**

The storage capacity (i.e. water volume) of the CCR surface impoundment at the time of the annual inspection was calculated based on the acreage of the CCR surface impoundment in the area where water is present, and the approximate depth of water within that area of the CCR surface impoundment. The water depth measurements of the CCR surface impoundment were collected at the time of the annual inspection.

From the 2016 topographic/bathymetric survey data, the area of the water surface of the CCR surface impoundment was approximately 0.35 acres. From the water depth data that was collected during the annual inspection, the average water depth within the CCR surface impoundment was approximately 2.93 feet. The water volume within the BGS Economizer Pond at the time of the annual inspection was approximately 1,650 cubic yards.

#### **2.3.5 Volume of Impounded CCR and Water (§257.83(b)(2)(v))**

The volume of impounded CCR and water (i.e. total volume, not including freeboard) within the BGS Economizer Pond at the time of the annual inspection was determined using information that was collected during the annual inspection, as well as from historical information that was previously provided from IPL. Historical information provided from IPL included a drawing of the original structural site preparation grading plan contours prepared by Black & Veatch (1965), as well as the most recent topographic/bathymetric survey of the BGS Economizer Pond completed by French-Reneker-Associates (2016).

The surveyed elevation of the top of water within the CCR surface impoundment at the time of the annual inspection was 546.22 feet. From the 2016 topographic survey of the economizer embankment, the average

elevation of the top of CCR along the economizer embankment was approximately 548 feet. From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation that was present prior to the construction of the BGS Economizer Pond and economizer embankment was approximately 521 feet. Thus, the interior storage height of the BGS Economizer Pond is approximately 25.22 feet and the interior storage height of the economizer embankment (not including the area of the BGS Economizer Pond) was approximately 27 feet.

The surface area of the BGS Economizer Pond was approximately 0.35 acres. Therefore, the volume of impounded CCR and water, not including freeboard, within the BGS Economizer Pond was approximately 14,240 cubic yards. The surface area of the economizer embankment (not including the area of the BGS Economizer Pond) was approximately 10.65 acres. Thus, the volume of impounded CCR within the economizer embankment was approximately 464,000 cubic yards. The total volume of impounded CCR and water within the BGS Economizer Pond and economizer embankment at the time of the annual inspection was approximately 478,240 cubic yards.

### **2.3.6 Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, as well as conducting the on-site visual inspection of the existing CCR surface impoundment, there have been no identified appearances of an actual or potential structural weakness of the existing CCR surface impoundment. Additionally, there were no identified issues with the structural integrity of the hydraulic structures (18-inch diameter high-density polyethylene pipe and rock filled overflow spillway) associated with the BGS Economizer Pond.

Regarding the existing conditions of the BGS Economizer Pond, there were no existing conditions identified along the upstream and downstream slopes of the embankments that were disrupting or have the potential to disrupt the operation and safety of the existing CCR surface impoundment.

### **2.3.7 Other Changes Affecting Stability or Operation of Impounding Structure (§257.83(b)(2)(vii))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, as well as discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no other identified changes that have affected the stability or operation of the BGS Economizer Pond since the previous annual inspection.

## **2.4 BGS Upper Ash Pond**

### **2.4.1 Changes in Geometry (§257.83(b)(2)(i))**

After conducting the annual inspection, as well as review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, and discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no identified changes in the geometry since the previous annual inspection.

### **2.4.2 Existing Instrumentation (§257.83(b)(2)(ii))**

Instrumentation that supports the operation of the BGS Upper Ash Pond includes a Parshall flume discharge structure and equipment to measure the flow of the discharged water, as well as a staff gauge to monitor the water elevation of the CCR surface impoundment. The instrumentation is in the



northeast corner of the BGS Upper Ash Pond and is associated with the NPDES Outfall 001 at BGS.

The flow data associated with the NPDES Outfall 001 discharge (i.e. maximum daily flow), since the previous annual inspection, was provided by IPL from May 1, 2020 and April 30, 2021. There were no recorded inundation events throughout this timeframe where the Mississippi River flooding sent back waters into the BGS Upper Ash Pond. Reviewing the provided flow data, the maximum daily flow recorded through NPDES Outfall 001 was 15.18 million gallons (January 11, 2021).

The staff gauge water elevation data, since the previous annual inspection, was provided by IPL. The staff gauge measurements were collected at the same time as the 7-day inspections. The water elevation data included measurements collected between April 2, 2020 and March 30, 2021. After review of the provided staff gauge water elevation data, the estimated maximum water elevation recorded within the BGS Upper Ash Pond was 528.74 feet (July 16, 2021).

#### **2.4.3 Depth and Elevation of Impounded CCR and Water (§257.83(b)(2)(iii))**

The approximate minimum, maximum, and present depths and elevations of the impounded CCR and water in the BGS Upper Ash Pond since the previous annual inspection were determined using information that was collected during the annual inspection, as well as from historical information that was previously provided from IPL.

At the time of the annual inspection a survey was completed to determine the present surface water elevation of the CCR surface impoundment. Additionally, depth measurements from the water surface to the top of CCR/sediment were obtained to determine present depths/elevations.

The historical information provided from IPL included staff gauge water elevation data since the previous annual inspection, a drawing of the original structural site preparation grading plan contours prepared by Black & Veatch (1965) which show the original contours prior to the construction of the BGS Upper Ash Pond, as well as the most recent topographic/bathymetric survey of the BGS Upper Ash Pond completed by French-Reneker-Associates (2016). Reviewing the information provided within the above-mentioned documents, as well as the data collected during the annual inspection, the following minimum, maximum, and present depths and elevations were approximated for the impounded CCR and water:

- At the time of the annual inspection, the water surface elevation was surveyed to be 527.67 feet, 1.57 feet below the crest of the north embankment of the CCR surface impoundment which has an elevation of 529.24 feet at the lowest point of the embankment.
- At the time of the annual inspection, the water depths that were measured within the CCR surface impoundment varied between 0.9 feet and 4.2 feet.
- From the water depth measurements at the time of the annual inspection, the elevation of the top of CCR/sediment varied between an elevation of 526.8 feet and 523.5 feet.
- From staff gauge water elevation data provided by IPL since the previous annual inspection, the minimum water elevation within the BGS Upper Ash Pond was recorded to be 527.7 feet (April 3, 2021). The maximum water elevation within the BGS Upper Ash Pond was recorded to be 529.2 (January 11, 2021).
- From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation that was

present prior to the construction of the BGS Upper Ash Pond was approximately 521 feet. Comparing the results from the water depth measurements at the time of the annual inspection to the 1965 drawing of the original structural site preparation grading plan bottom contour elevation, the deposition thickness within the BGS Upper Ash Pond varied between 5.8 feet to 2.5 feet.

#### **2.4.4 Storage Capacity of Impounding Structure (§257.83(b)(2)(iv))**

The storage capacity (i.e. water volume) of the CCR surface impoundment at the time of the annual inspection was calculated based on the acreage of the CCR surface impoundment in the area where water is present, and the approximate depth of water within that area of the CCR surface impoundment. The water depth measurements of the CCR surface impoundment were collected at the time of the annual inspection.

From the 2016 topographic/bathymetric survey data, the area of the water surface of the CCR surface impoundment was approximately 7.7 acres. From the water depth data that was collected during the annual inspection, the average water depth within the CCR surface impoundment was approximately 3.20 feet. Thus, the water volume within the BGS Upper Ash at the time of the annual inspection was approximately 39,750 cubic yards.

#### **2.4.5 Volume of Impounded CCR and Water (§257.83(b)(2)(v))**

The volume of impounded CCR and water (i.e. total volume, not including freeboard) within the BGS Upper Ash Pond at the time of the annual inspection was determined using information that was collected during the annual inspection, as well as from historical information that was previously provided from IPL. Historical information provided from IPL included a drawing of the original structural site preparation grading plan contours prepared by Black & Veatch (1965), as well as the most recent

topographic/bathymetric survey of the BGS Upper Ash Pond completed by French-Reneker-Associates (2016).

The surveyed elevation of the top of water within the CCR surface impoundment at the time of the annual inspection was 527.67 feet. From the 2016 topographic survey of the BGS Upper Ash Pond, the average elevation of the top of CCR/sediment outside the footprint of the water surface was approximately 529 feet. From the 1965 drawing of the original structural site preparation grading plan contours, the bottom contour elevation that was present prior to the construction of the BGS Upper Ash Pond was approximately 521 feet. Thus, the interior storage height of the BGS Upper Ash Pond (water portion) was approximately 6.67 feet and the interior storage height of the CCR/sediment located outside the footprint of the water surface was approximately 8 feet.

The surface area of the BGS Upper Ash Pond, in the area where water is present, was approximately 7.7 acres. Thus, the volume of impounded CCR and water within the BGS Upper Ash Pond, within the area where water was present but not including freeboard, was approximately 82,900 cubic yards. The surface area of the BGS Upper Ash Pond, in the area located outside of the footprint of the water portion, was approximately 5.6 acres. Thus, the volume of impounded CCR within the BGS Upper Ash Pond, in the area located outside of the footprint of the water portion, was approximately 72,300 cubic yards. The total volume of impounded CCR and water within the BGS Upper Ash Pond at the time of the annual inspection was approximately 155,200 cubic yards.

#### **2.4.6 Structural Weaknesses and Disruptive Conditions (§257.83(b)(2)(vi))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, discussions with

BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, as well as conducting the on-site visual inspection of the existing CCR surface impoundment, there have been no identified appearances of an actual or potential structural weakness of the existing CCR surface impoundment. Additionally, there were no identified issues with the structural integrity of the hydraulic structures (NPDES Outfall 001) associated with the BGS Upper Ash Pond.


Regarding the existing conditions of the BGS Upper Ash Pond, there were no existing conditions identified along the upstream and downstream slopes of the embankments that were disrupting or have the potential to disrupt the operation and safety of the existing CCR surface impoundment.

#### **2.4.7 Other Changes Affecting Stability or Operation of Impounding Structure (§257.83(b)(2)(vii))**

After review of available information provided by BGS pertaining to the status and condition of the existing CCR surface impoundment, as well as discussions with BGS facility personnel who oversee and maintain the operation, maintenance, and inspection activities of the existing CCR surface impoundment, there have been no other identified changes that have affected the stability or operation of the BGS Upper Ash Pond since the previous annual inspection.

### 3. CERTIFICATION

To meet the requirements of 40 CFR 257.83(b), I Mark W. Loerop hereby certify that I am a licensed professional engineer in the State of Iowa; and that, to the best of my knowledge, all information contained in this document is correct and the document was prepared in compliance with all applicable requirements in 40 CFR 257.83(b).

By:   
\_\_\_\_\_

Name: MARK LOEROP

Date: JUNE 24, 2021

