



Interstate Power and Light Co.
An Alliant Energy Company

Sutherland Station
3001 East Main Street Road
P.O. Box 537
Marshalltown, IA 50158-0537

Office: 641.754.4900
www.alliantenergy.com

September 19, 2017

Mr. Mark Loerop
Hard Hat Services, Inc.
932 N. Wright Street, Suite 160
Naperville, IL 60563

Subject: Annual CCR Surface Impoundment Inspection Report
Interstate Power and Light Company – Sutherland Generating Station
Marshalltown, IA

Mr. Loerop:

Thank you for preparing the annual inspection report that is required under 40 CFR 257.83(b) of the Coal Combustion Residuals (CCR) Rule. We have carefully reviewed the findings and recommendations contained in the report. We understand that you did not observe any indication of an actual or potential structural weakness within the existing CCR surface impoundments. Thus, we have focused on improving the vegetative conditions, as recommended. In response to the report, we have completed the following measures:

- The dense and tall vegetation has been removed from the upstream slope of the south embankment, and from the upstream and downstream slopes of the east embankment on the SGS Main Pond.

The work was completed as soon as feasible and in a manner that protects the safety of our employees and meets all local, state, and federal requirements. We will continue to manage the vegetation along the embankments to facilitate effective inspection, and we look forward to your next annual inspection.

Sincerely,

A handwritten signature in black ink, appearing to read "Craig Crawford".

Craig Crawford
Plant Manager

Cc: Jeff Maxted, Marney Hoefer – Alliant Energy
George Kueny – Sutherland Generating Station